



CONDITION REPORT

2020 BMW X1 xDrive25e (F48) X1 xDrive25e (F48) 162HP

2020 | 116732 KM | auto | Petrol | 162 kw

Seller Disclosure



 **MANHEIM**
Auction Services
COX AUTOMOTIVE

4264LKT

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	black
HP	162 kw
VIN	WBA71AB0105S35148

Technical Inspection

DUA	Nein
Registration Date	30.10.2020
Last Service Date	-

-  2^a CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



POSIBILIDAD EXTRA VIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -