



CONDITION REPORT

2024 BMW M235i xDrive Gran Coupé (F44) M235i xDrive Gran Coupé (F44) 225HP

2024 | 15730 KM | auto | Petrol | 225 kw

Seller Disclosure



4526MRG

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	black
HP	225 kw
VIN	WBA11AL0807P42251
Technical Inspection	
DUA	Nein
Registration Date	08.05.2024
Last Service Date	-

- 2^o CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIDIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO
Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid


Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -