



# CONDITION REPORT

2019 BMW X1 X1 1.5 SDRIVE16D 116HP

2019 | 99700 KM | Manual | DIESEL | 116 hp

Seller Disclosure



**8881LDC**

Engine Size	1496 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	BLANCO
HP	116 hp
VIN	WBA31AC0105P42628
<b>Technical Inspection</b>	
DUA	Nein
Registration Date	12.12.2019
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



## Zubehör

## Öffentliche Anmerkungen

## Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Standort** Madrid  
**Auction Centre** Madrid

## Inspection

**Standort** Madrid  
**Auction Centre** Madrid

## Damage Assessment

---



Damage Detail : -

Damage Type : -

Damage Size : -