



CONDITION REPORT

2020 BMW X7 xDrive30d (G07) X7 xDrive30d (G07) 195HP

2020 | 101319 KM | auto | DIESEL | 195 kw

Seller Disclosure



 **MANHEIM**
Auction Services
COX AUTOMOTIVE

0584LJT

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Sophistograu, efecto brillo metalizado
HP	195 kw
VIN	WBACW810809D41313
Technical Inspection	
DUA	Nein
Registration Date	08.09.2020
Last Service Date	-



2ª CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRA VIO FT
EQUIPAMIENTO:
ASI.CAL ; ASI.DEP ; ASI.DEP ; Park Assist. ; ASIST.LUZ CARRET. ; AUT ; Driv.Asist. ; Enganche remolque ; HIFI H/K ; HUD ; Luz láser ; PAQ.innov. ; SCA

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -