



CONDITION REPORT

2019 OPEL COMBO COMBO 1.6 TD 74KW EXPRESS 650KG
S/S SWB 100HP

2019 | 40937 KM | Manual | DIESEL | 100 hp

Seller Disclosure



2096LDB

Engine Size	1560 cm3
Sitze	-
Anzahl der Türen	3
Body Style	-
Body Colour	BLANCO
HP	100 hp
VIN	W0VEFYHYCLN500716
Technical Inspection	
DUA	Nein
Registration Date	05.12.2019
Last Service Date	-

- 2º CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim>
TRANSPORTE

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid


Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -