



CONDITION REPORT

2020 BMW SERIE 1 SERIE 1 2.0 118D 150HP

2020 | 102013 KM | Manual | DIESEL | 150 hp


Seller Disclosure



7370LLW

Engine Size	1995 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	NEGRO GRIS METALIZ
HP	150 hp
VIN	WBA7M910X07H44623
Technical Inspection	
DUA	Nein
Registration Date	23.12.2020
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid


Damage Assessment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -