



CONDITION REPORT

2021 Nissan E-NV200 Nissan e-NV200 Furgón 4p 40 kWh
PROFESIONAL furgón HP

2021 | 56114 KM | auto | electric |

Seller Disclosure



9133LNG

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Iceberg Blanco sólido
HP	-
VIN	VSKHAAME0U0620846
Technical Inspection	
DUA	Nein
Registration Date	24.03.2021
Last Service Date	-



2º CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid


Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -