



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 123601 KM | auto | DIESEL | 85 kw

Seller Disclosure



2685LNG

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	85 kw
VIN	WBA7M710107H94217
Technical Inspection	
DUA	Nein
Registration Date	23.03.2021
Last Service Date	-

-  2ª CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
EQUIPAMIENTO:
;
ACC.CONF ; ASI.CAL ; CC ; LED ;
PAQ.Business ; PDC ; STEPTRONIC

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -