



CONDITION REPORT

2019 BMW X1 X1 SDRIVE18DA BUSINESS(CAM) 150HP

2019 | 148215 KM | Manual | DIESEL | 150 hp

Seller Disclosure



3898KTN

Engine Size	1995 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	BLANCO
HP	150 hp
VIN	WBAJH51090EK97326
Technical Inspection	
DUA	Nein
Registration Date	13.02.2019
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen


Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Standort** Madrid
Auction Centre Madrid

Inspection

Standort Madrid
Auction Centre Madrid

Damage Assessment



Damage Detail : -
Damage Type : -
Damage Size : -