



CONDITION REPORT

2023 DS DS 4 DS 4 TROCADERO 1.5 BLUEHDI 130CV AUT
HP


2023 | 76158 KM | auto | DIESEL |

Seller Disclosure



7688MDN

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	GRIS
HP	-
VIN	VR1FCYHZTN1046292
Technical Inspection	
DUA	Nein
Registration Date	27.01.2023
Last Service Date	-
2 ^a CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör	Öffentliche Anmerkungen	Inspection
	-	Standort Auction Centre - Madrid

Inspection
Standort Auction Centre - Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -