



# CONDITION REPORT

2020 BMW X1 xDrive18d (F48) X1 xDrive18d (F48) 110HP

2020 | 131394 KM | auto | DIESEL | 110 kw

Seller Disclosure



**5498LKF**

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Glaciersilber metalizado
HP	110 kw
VIN	WBA31AD0905R22356
<b>Technical Inspection</b>	
DUA	Nein
Registration Date	30.09.2020
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



**Zubehör**

---

**Öffentliche Anmerkungen**

---

**Inspection**

---

DOCUMENTACION EN CUSTODIA DE  
GESTORIA<BR>EQUIPAMIENTO:<BR>;  
ASI.CAL ; ASI.DEP ; ASI.DEP ;  
ASIST.APARC ; AUT ; CAM.TRAS\* ; CC ;  
L.Sport ; L.Sport ; LED ; NAV\* ;  
PAQ.Exclusive ; PDC ; Perform.Ctrl ;  
Volante M

**Standort** -  
**Auction Centre** Madrid


**Inspection**

---


**Standort** -  
**Auction Centre** Madrid

**Damage Assesment**


---




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -