



CONDITION REPORT

2019 Nissan E-NV200 Furgón 4p 40 kWh PROFESIONAL
furgón 80KW (109CV) 4 HP

2019 | 38234 KM | auto | |

Seller Disclosure



3834KTG

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco
HP	-
VIN	VSKHAAME0U0606756
Technical Inspection	
DUA	Nein
Registration Date	30.01.2019
Last Service Date	-

-  2ª CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Inspection

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -