



CONDITION REPORT

2020 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2020 | 53284 KM | auto | electric | 125 kw

Seller Disclosure



6251LKX

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Fluid Black con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210107F65102
Technical Inspection	
DUA	Nein
Registration Date	11.11.2020
Last Service Date	-

- ✗ 2ª CHAVE
- ✗ SERVICEHEFT
- ✗ VAT
- ✗ Verkauft wie gesehen



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -