



CONDITION REPORT

2020 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2020 | 85093 KM | auto | electric | 125 kw

Seller Disclosure



8033LJT

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Mineralgrau con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210807F69647
Technical Inspection	
DUA	Nein
Registration Date	10.09.2020
Last Service Date	-



2ª CHAVE



SERVICEHEFT



VAT













Verkauft wie gesehen



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment

			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -
			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -
			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	