



CONDITION REPORT

2021 BMW X1 xDrive25e (F48) X1 xDrive25e (F48) 162HP

2021 | 77490 KM | auto | Petrol | 162 kw

Seller Disclosure



8897LTW

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	black
HP	162 kw
VIN	WBA71AB0905U46811
Technical Inspection	
DUA	Nein
Registration Date	17.11.2021
Last Service Date	-



2^a CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment

			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -
			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -
			
Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	Damage Detail : - Damage Type : - Damage Size : -	