



CONDITION REPORT

2019 DS DS 3 CROSSBACK BlueHDi 73 kW Manual SO CHIC
100HP

2019 | 88993 KM | Manual | DIESEL | 100 hp

Seller Disclosure



2501LDH

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VR1UCYHYJKW132739
Technical Inspection	
DUA	Nein
Registration Date	19.12.2019
Last Service Date	-

-  2ª CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Standort	Madrid
Auction Centre	Madrid

Inspection

Standort	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -