



CONDITION REPORT

2019 Volkswagen CADDY Profesional Furgon 1.4 TGI 81kW
BM 110HP

2019 | 1 KM | Manual | lpg | 110 hp

Seller Disclosure



9015KZV

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco candy sÃ³lido
HP	110 hp
VIN	WV1ZZZ2KZKX135612
Technical Inspection	
DUA	Nein
Registration Date	29.08.2019
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort	Madrid
Auction Centre	Madrid


Inspection

Standort	Madrid
Auction Centre	Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -