



CONDITION REPORT

2019 Ford Transit Courier Kombi 1.0 EcoBoost 75kW Trend
100HP

2019 | 1 KM | Manual | Petrol | 100 hp


Seller Disclosure



4672KYP

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	WF0NXXTACNKL64327
Technical Inspection	
DUA	Nein
Registration Date	03.07.2019
Last Service Date	-

- 2^a CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort Madrid
Auction Centre Madrid

Inspection

Standort Madrid
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -