



CONDITION REPORT

2019 BMW X3 Xdrive20d 190HP

2019 | 67011 KM | auto | DIESEL | 190 hp

Seller Disclosure



4429KWC

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	black
HP	190 hp
VIN	WBATX350X0NC58340
Technical Inspection	
DUA	Nein
Registration Date	04.08.2019
Last Service Date	-

- 2^a CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Standort	Madrid
Auction Centre	Madrid

Inspection

Standort	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -