



CONDITION REPORT

2020 DS DS 7 CROSSBACK BlueHDi DE 96kW (130CV)
PERFORMANCE LINE todoterre HP

2020 | 77831 KM | Manual | DIESEL |

Seller Disclosure



2848LDX

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco Banquise - P0WP
HP	-
VIN	VR1JCYHZJKY225213
Technical Inspection	
DUA	Nein
Registration Date	17.01.2020
Last Service Date	-

- 2^a CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL


Inspection

Standort	-
Auction Centre	Madrid

Inspection

Standort	-
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -