



CONDITION REPORT

2021 BMW X2 X2 2.0 SDRIVE20D AUTO 190HP

2021 | 115434 KM | auto | DIESEL | 190 hp

Seller Disclosure



5021LMN

Engine Size	1995 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	A96MINERALWEISS META
HP	190 hp
VIN	WBAYK910205S94792
Technical Inspection	
DUA	Nein
Registration Date	10.02.2021
Last Service Date	-

- ☒ 2ª CHAVE
- ☒ SERVICEHEFT
- ☒ VAT
- ☒ Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

<https://www.manheimtransportautoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -