



CONDITION REPORT

2021 Mazda CX-5 CX-5 (O)2.2 D 110KW ZENITH SAFETY 2WD
150HP

2021 | 116517 KM | Manual | DIESEL | 150 hp

Seller Disclosure

0092LNB

Engine Size	2191 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	METALIZADA
HP	150 hp
VIN	JMZKF6W1690121697
Technical Inspection	
DUA	Nein
Registration Date	10.03.2021
Last Service Date	-

- ✗ 2º CHAVE
- ✗ SERVICEHEFT
- ✓ VAT
- ✗ Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Standort
Auction Centre - Madrid

Inspection

Standort
Auction Centre - Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -