



CONDITION REPORT

2019 BMW X1 X1 SDRIVE18D 150HP

2019 | 108851 KM | Manual | DIESEL | 150 hp

Seller Disclosure



7769KVC

Engine Size	1995 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	yellow
HP	150 hp
VIN	WBAJH51050EK94231

Technical Inspection

DUA	Nein
Registration Date	05.03.2019
Last Service Date	-

- ✗ 2ª CHAVE
- ✗ SERVICEHEFT
- ✓ VAT
- ✗ Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

CALCULA TU TRANSPORTE

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -