



CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON 1.6 CRDI 100KW 48V
STYLE DT 2WD 136HP

2020 | 92938 KM | Manual | | 136 hp

Seller Disclosure



9268LGK

Engine Size	1598 cm3
Sitze	-
Anzahl der Türen	5
Body Style	-
Body Colour	POLAR WHITE
HP	136 hp
VIN	TMAJ3817GLJ044804
Technical Inspection	
DUA	Nein
Registration Date	22.05.2020
Last Service Date	-

- ✘ 2ª CHAVE
- ✘ SERVICEHEFT
- ✔ VAT
- ✘ Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Standort** -
TRANSPORTE **Auction Centre** Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -