



CONDITION REPORT

2019 BMW i BMW i3 (I01) BMW i3 (I01) 125HP

2019 | 102617 KM | auto | electric | 125 kw

Seller Disclosure



0267KYN

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Fluid Black con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210707E07749
Technical Inspection	
DUA	Nein
Registration Date	28.06.2019
Last Service Date	-

-  2ª CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -