



CONDITION REPORT

2024 BMW 118d (F40) 118d (F40) 110HP

2024 | 19485 KM | auto | DIESEL | 110 kw

Seller Disclosure



8796MPB

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	black
HP	110 kw
VIN	WBA7M910X07P23221
Technical Inspection	
DUA	Nein
Registration Date	19.03.2024
Last Service Date	-
 2 ^e CHAVE	
 SERVICEHEFT	
 VAT	
 Verkauft wie gesehen	



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -