




CONDITION REPORT

2023 BMW iX1 xDrive30 (U11) iX1 xDrive30 (U11) 200HP
2023 | 15013 KM | auto | electric | 200 kw
Seller Disclosure



9603MKB

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	white
HP	200 kw
VIN	WBY61EF0105X49001
Technical Inspection	
DUA	Nein
Registration Date	30.08.2023
Last Service Date	-
2 ^a CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort

Auction Centre

-

Madrid

Inspection

Standort

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -