



CONDITION REPORT

2020 Jaguar E-PACE E-PACE 2.0D 110kW 4WD Auto HP

2020 | 123571 KM | auto | DIESEL |

Seller Disclosure



7898LJG

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Gris
HP	-
VIN	SADFA2BN4L1004938
Technical Inspection	
DUA	Nein
Registration Date	11.08.2020
Last Service Date	-

-  2^e CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

MUY IMPORTANTE: REVISAR
PERITACION PARA COMPROBAR
DAÑOS


Standort
Auction Centre

-
Manheim Directo,
S.L.U.


Inspection

Standort -
Auction Centre Manheim Directo,
S.L.U.

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -