



CONDITION REPORT

2021 Citroen JUMPER Citroen Jumper BlueHDi 103KW
(140CV) Furgón 35L3H2 HP

2021 | 104583 KM | Manual | DIESEL |

Seller Disclosure



0041LSZ

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco Hielo (opaco)
HP	-
VIN	VF7YCBNFC12S94175
Technical Inspection	
DUA	Nein
Registration Date	24.09.2021
Last Service Date	-



2º CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -