



CONDITION REPORT

2021 BMW 318d Touring (G21) 318d Touring (G21) 110HP

2021 | 119621 KM | auto | DIESEL | 110 kw

Seller Disclosure



3860LNK

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	BMW Individual Tanzanite Blue metallic
HP	110 kw
VIN	WBA6L310X0FL10636
Technical Inspection	
DUA	Nein
Registration Date	29.03.2021
Last Service Date	-

- 2^a CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort
Auction Centre

Madrid-ES34
Madrid

Inspection

Standort Madrid-ES34
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -