



CONDITION REPORT

2020 BMW 116d (F40) 116d (F40) 85HP

2020 | 102369 KM | auto | DIESEL | 85 kw

Seller Disclosure



5142LFX

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710007F22712
Technical Inspection	
DUA	Nein
Registration Date	28.02.2020
Last Service Date	-



2^a CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort Madrid-ES34
Auction Centre Madrid

Inspection

Standort Madrid-ES34
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -