



CONDITION REPORT

2024 BMW X1 xDrive20d (U11) X1 xDrive20d (U11) 110HP
2024 | 25177 KM | auto | DIESEL | 110 kw
Seller Disclosure



6408MNZ

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Spacesilber
HP	110 kw
VIN	WBA41EG0405Y87619
Technical Inspection	
DUA	Nein
Registration Date	15.03.2024
Last Service Date	-
2 ^a CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort

Auction Centre

Valencia-ES28
Madrid

Inspection

Standort

Auction Centre

Valencia-ES28
Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -