



CONDITION REPORT

2022 BMW 116d (F40) 116d (F40) 85HP

2022 | 66381 KM | auto | DIESEL | 85 kw

Seller Disclosure



7727LWL

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	85 kw
VIN	WBA7M710207K65971
Technical Inspection	
DUA	Nein
Registration Date	22.02.2022
Last Service Date	-



2ª CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO	Standort Auction Centre	Sevilla-ES50 Madrid
--	--	------------------------

Inspection

Standort	Sevilla-ES50
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -