



CONDITION REPORT

2019 Renault TRAFIC Furgon 29 L1H1 Energy BluedCi 88 kW
120HP

2019 | 113763 KM | Manual | DIESEL | 120 hp

Seller Disclosure



4259LCL

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco casablanca (o
HP	120 hp
VIN	VF1FL000564306192
Technical Inspection	
DUA	Nein
Registration Date	14.11.2019
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort	-
Auction Centre	Madrid

Inspection

Standort	-
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -