



CONDITION REPORT

2020 Jaguar E-PACE 2.0D 110kW S 4WD Auto 150HP

2020 | 136055 KM | auto | DIESEL | 150 hp

Seller Disclosure



3829LFW

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Corris
HP	150 hp
VIN	SADFA2BN8L1002240
Technical Inspection	
DUA	Nein
Registration Date	27.02.2020
Last Service Date	-



2^a CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort -
Auction Centre Madrid


Inspection

Standort -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -