



CONDITION REPORT

2022 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2022 | 26667 KM | auto | electric | 125 kw

Seller Disclosure



8411LWC


Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Capparisweis con acentuación BMW i Blau
HP	125 kw
VIN	WBY8P210007K48425
Technical Inspection	
DUA	Nein
Registration Date	31.01.2022
Last Service Date	-
2º CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	




Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort Auction Centre - Manheim Directo, S.L.U.

Inspection
Standort Auction Centre - Manheim Directo, S.L.U.


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -