



CONDITION REPORT

2020 DS DS 3 CROSSBACK BlueHdi 73 kW Manual SO CHIC
100HP

2020 | 122024 KM | Manual | DIESEL | 100 hp

Seller Disclosure



0781LJX

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VR1UCYHYJLW018122
Technical Inspection	
DUA	Nein
Registration Date	17.09.2020
Last Service Date	-



2^a CHAVE



SERVICEHEFT



VAT



Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort	-
Auction Centre	Madrid

Inspection

Standort	-
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -