



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 42920 KM | auto | DIESEL | 85 kw

Seller Disclosure



2839LNK

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	-
HP	85 kw
VIN	WBA7M710107H94248
Technical Inspection	
DUA	Nein
Registration Date	29.03.2021
Last Service Date	-
 2 ^a CHAVE	
 SERVICEHEFT	
 VAT	
 Verkauft wie gesehen	



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -