



CONDITION REPORT

2024 BMW 116d (F40) 116d (F40) 85HP
2024 | 10255 KM | Manual | DIESEL | 85 kw
Seller Disclosure



0293MMV

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	-
HP	85 kw
VIN	WBA7M710407N51000
Technical Inspection	
DUA	Nein
Registration Date	18.01.2024
Last Service Date	-
2 ^a CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort

Auction Centre

-

Madrid

Inspection


Standort

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -