



CONDITION REPORT

2022 BMW 318d Berlina (G20) 318d Berlina (G20) 110HP

2022 | 120107 KM | auto | DIESEL | 110 kw

Seller Disclosure



5133LZD

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	-
HP	110 kw
VIN	WBA5V310X0FN15654
Technical Inspection	
DUA	Nein
Registration Date	12.07.2022
Last Service Date	-

-  2^a CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Standort

Auction Centre

-

Madrid

Inspection

Standort

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -