



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 94791 KM | auto | DIESEL | 85 kw

Seller Disclosure



4886LNB

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710505T32283

Technical Inspection

DUA	Nein
Registration Date	11.03.2021
Last Service Date	-

-  2^a CHAVE
-  SERVICEHEFT
-  VAT
-  Verkauft wie gesehen



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -