



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 89125 KM | Manual | DIESEL | 85 kw

Seller Disclosure





5817LNS

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710305T28233
Technical Inspection	
DUA	Nein
Registration Date	14.04.2021
Last Service Date	-
2 ^a CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör	Öffentliche Anmerkungen	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Standort - Auction Centre Madrid

Inspection
Standort - Auction Centre Madrid

Damage Assesment	
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -