



CONDITION REPORT

2021 MERCEDES Vito 111 CDI Larga 114HP

2021 | 137329 KM | Manual | DIESEL | 114 hp

Seller Disclosure



3816LMP

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco artico
HP	114 hp
VIN	WDF44760313617332

Technical Inspection

DUA	Nein
Registration Date	16.02.2021
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Standort	-
Auction Centre	Madrid

Inspection

Standort	-
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -