



CONDITION REPORT

2022 DS DS 3 CROSSBACK PureTech 73 kW Manual
PERFORMANCE LINE 100HP

2022 | 91841 KM | Manual | | 100 hp

Seller Disclosure



4583LWP

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco banquise
HP	100 hp
VIN	VR1URHNEKMW108879
Technical Inspection	
DUA	Nein
Registration Date	28.02.2022
Last Service Date	-
2 ^e CHAVE	
SERVICEHEFT	
VAT	
Verkauft wie gesehen	



Zubehör

Öffentliche Anmerkungen

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Técnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL


Standort
Auction Centre

-
Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -