



CONDITION REPORT

2019 Citroen C3 BlueHDi 73KW (100CV) S&S FEEL 99HP

2019 | 66133 KM | Manual | DIESEL | 99 hp


Seller Disclosure



7229KWV

Engine Size	-
Sitze	-
Anzahl der Türen	-
Body Style	-
Body Colour	Blanco
HP	99 hp
VIN	VF7SXYHYPKT586918
Technical Inspection	
DUA	Nein
Registration Date	07.05.2019
Last Service Date	-

- 2ª CHAVE
- SERVICEHEFT
- VAT
- Verkauft wie gesehen



Zubehör

Öffentliche Anmerkungen

IMPORTANTE: VER PERITACIÓN
(Informe Técnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL


Inspection

Standort -
Auction Centre Madrid

Inspection

Standort -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -