



CONDITION REPORT

2024 BMW M440d xDrive Cabrio (G23) M440d xDrive Cabrio (G23) 250HP

2024 | 16523 KM | auto | Diesel | 250 kw



Seller Disclosure



8870MNM

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	250 kw
VIN	WBA31AU060CR69341
Technical Inspection	
DUA	No
Registration Date	26/02/2024
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT


EQUIPAMIENTO:
; ACC.CONF ;
ASI.CAL ; Park Assist. ; ASIST.LUZ
CARRET. ; AUT DEP ; D.Dep ; Dif.M ;
Driv.Asist. ; Freno M ; HIFI ; Luz láser ;
Mild-Hybrid 48V ; PAQ.M* ; PAQ.M* ;
SUSP. M ; Volante calef. ; Volante M

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -