



# CONDITION REPORT

2024 BMW M235i xDrive Gran Coupé (F44) M235i xDrive Gran Coupé (F44) 225HP

2024 | 15730 KM | auto | Petrol | 225 kw

Seller Disclosure



**4526MRG**

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	black
HP	225 kw
VIN	WBA11AL0807P42251
<b>Technical Inspection</b>	
DUA	No
Registration Date	08/05/2024
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



**Equipment**

---

**Public Notes**

---

**Inspection**

---

POSIBILIDAD EXTRAVIDIO FT<BR><a href="http://soportemanheim.es/E/4526MRG.htm" target="\_blank">CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO</a>

**Location** -  
**Auction Centre** Madrid


**Inspection**

---


**Location** -  
**Auction Centre** Madrid

**Damage Assesment**


---




Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -




Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -