



# CONDITION REPORT

2019 BMW X1 X1 1.5 SDRIVE16D 116HP

2019 | 99700 KM | Manual | Diesel | 116 hp

Seller Disclosure



**8881LDC**

Engine Size	1496 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	BLANCO
HP	116 hp
VIN	WBA31AC0105P42628
Technical Inspection	
DUA	No
Registration Date	12/12/2019
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



## Equipment

## Public Notes

## Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Location** Madrid  
**Auction Centre** Madrid **CALCULA TU TRANSPORTE**

## Inspection

**Location** Madrid  
**Auction Centre** Madrid

## Damage Assessment

---



Damage Detail : -  
Damage Type : -  
Damage Size : -