



# CONDITION REPORT

2020 Mini Cooper SE (F56) Cooper SE (F56) 135HP

2020 | 72427 KM | auto | electric | 135 kw

Seller Disclosure



1031LLS

|                                                                                                           |                   |
|-----------------------------------------------------------------------------------------------------------|-------------------|
| Engine Size                                                                                               | -                 |
| Seats                                                                                                     | -                 |
| Number of Doors                                                                                           | -                 |
| Body Style                                                                                                | -                 |
| Body Colour                                                                                               | White Silver      |
| HP                                                                                                        | 135 kw            |
| VIN                                                                                                       | WMWXP310102N98482 |
| Technical Inspection                                                                                      |                   |
| DUA                                                                                                       | No                |
| Registration Date                                                                                         | 18/12/2020        |
| Last Service Date                                                                                         | -                 |
|  2 <sup>a</sup> CHAVE |                   |
|  Service History     |                   |
|  VAT                 |                   |
|  Sold as Seen        |                   |



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT<BR><a href="http://soportemanheim.es/E/1031LLS.htm" target="\_blank">CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO</a>

Location -

Auction Centre Madrid

Inspection

Location -

Auction Centre Madrid

Damage Assesment



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -