



CONDITION REPORT

2019 Mini Cooper S E All4 (F60) Cooper S E All4 (F60) 165HP

2019 | 140510 KM | auto | Petrol | 165 kw

Seller Disclosure



4511LCW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Melting Silver
HP	165 kw
VIN	WMWYU710403L61113

Technical Inspection

DUA	No
Registration Date	28/11/2019
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT


EQUIPAMIENTO:
; ACC.CONF ;
ASI.DEP ; ASI.DEP ; ASIST.APARC ; AUT
; CAM.TRAS* ; CC ; LED ; NAV* ; PDC ;
Perform.Ctrl

Location Madrid
Auction Centre Madrid


Inspection

Location Madrid
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -